

## April Dam report

By Ed Zimmermann

I monitored the dam during every heavy rain event we have had recently. There were no issues observed. No seepage or sloughing on the entire dam. The spillway never exceeded a rise greater than 6 inches. Our Emergency Action Plan requires initial activation at a 1-foot rise over the spillway or signs of failure, so no activation was necessary. An FYI, 1 foot rise initiates a warning to the public, a 2-foot rise initiates evacuation in the inundation area.

I inspected the dam after the earthquake and no movement on the dam was observed.

Planning on a committee meeting in May.