

Jan. 2022 Dam report:

Kiley did survey of dam at the end of Nov. Spoke with Joe Hudak on 1/13, estimates 2 months for the complete report to be ready. This is the hydrologic study report required before the state will review pipe repair plans. Once report is complete, the state needs to review it.

I did our self inspection in Dec. No issues.

Small pine trees at toe of dam by access road need to be removed as per our annual inspection done by Kiley. These are small trees, and could be done by volunteers rather than hiring someone. The area is ten feet in from toe.