

July Clubhouse Report

We had a mini clean-up day where we worked on cleaning, organizing and clearing out the basement.

Barryville Exterminating mitigated the spider webs and treated the interior and exterior of the clubhouse. I suggest we have treatments three times a year so we can stay ahead of the buggers.

After the extremely heavy rains we experienced earlier in the month, I discovered that quite a bit of water found its way into the basement especially in the corner where the electric panel is located. One can clearly see that the water has infiltrated into the blocks, as well as where it seeps into the basement. I feel we should consider putting off the aesthetic upgrades of the clubhouse and concentrate on the structural issues.

