

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
0374022	NPW	Walker Lake	06/29/2026 02:45 PM	06/29/2026

Laboratory Information:

Incubation: 6/29/26 17:30

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enum) (4)	80	cfu/100mL	0	TC	06/30/2026 05:15 PM	6-26W59948	East Shore
m-ColiBlue24	E. coli (Enum) (4)	32	cfu/100mL	0	TC	06/30/2026 05:15 PM	6-26W59949	West Shore (E)

Date: 06/30/2026

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer".

Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 06/30/2026

Reviewed By:

A handwritten signature in black ink, which appears to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT