

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
6853564	NPW	Walker Lake	06/15/2026 11:50 AM	06/15/2026

Laboratory Information:

Incubation: 6/15/26 15:40

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enum) (2)	10	cfu/100mL	2.0	TC	06/16/2026 03:26 PM	6-26W59042	East Shore (E)
m-ColiBlue24	E. coli (Enum) (2)	16	cfu/100mL	2.0	TC	06/16/2026 03:26 PM	6-26W59043	West Shore (E)

Date: 06/16/2026

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E):

(E) Results based upon colony counts outside the method's ideal range.

Date: 06/16/2026

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT