

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
0567569	NPW	Walker Lake	06/22/2026 02:55 PM	06/22/2026

Laboratory Information:

Incubation: 6/22/26 17:38

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enum) (2)	12	cfu/100mL	2.0	TC	06/23/2026 05:26 PM	6-26W59546	East Shore (E)
m-ColiBlue24	E. coli (Enum) (2)	14	cfu/100mL	2.0	TC	06/23/2026 05:26 PM	6-26W59547	West Shore (E)

Date: 06/23/2026

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 06/23/2026

Reviewed By:

A handwritten signature in black ink, which appears to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT