

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
4118823	NPW	Walker Lake	06/26/2025 10:05 AM	06/26/2025

Laboratory Information:

Incubation: 6/26/25 16:04

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	196	cfu/100mL	0	TC	06/27/2025 03:53 PM	6-25W44146	East Shore

Date: 06/27/2025

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer".

Michael J. Coyer, Ph.D., F-ABFT