

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
9334700	NPW	Walker Lake	07/06/2026 04:00 PM	07/06/2026

Laboratory Information:

Incubation: 7/6/26 17:58

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enum) (4)	692	cfu/100mL	0	TC	07/07/2026 05:53 PM	7-26W60443	East Shore (E)(SB2)
m-ColiBlue24	E. coli (Enum) (4)	708	cfu/100mL	0	TC	07/07/2026 05:56 PM	7-26W60444	West Shore (E)(SB2)

Date: 07/07/2026

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

(SB2): (SB2) Sample of water from bathing beach is considered contaminated per 28 Pa.
Code §18.28.

Date: 07/07/2026

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT