

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
8744956	NPW	Walker Lake	07/21/2025 10:45 AM	07/21/2025

Laboratory Information:

Incubation: 7/21/25 15:40

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	16	cfu/100mL	0	TC	07/22/2025 03:28 PM	7-25W45495	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	20	cfu/100mL	0	TC	07/22/2025 03:28 PM	7-25W45496	West Shore (E)

Date: 07/22/2025

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E):

(E) Results based upon colony counts outside the method's ideal range.

Date: 07/22/2025

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT