

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
7965795	NPW	Walker Lake	06/16/2025 11:15 AM	06/16/2025

Laboratory Information:

Incubation: 6/16/25 16:30

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	16	cfu/100mL	0	TC	06/17/2025 04:16 PM	6-25W43394	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	8	cfu/100mL	0	TC	06/17/2025 04:16 PM	6-25W43395	West Shore (E)

Date: 06/17/2025

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E):

(E) Results based upon colony counts outside the method's ideal range.

Date: 06/17/2025

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT