

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


| <u>Chain of Custody Number</u> | <u>Sample Type</u> | <u>Project ID</u> | <u>Sample Date/Time</u> | <u>Accession Date</u> |
|--------------------------------|--------------------|-------------------|-------------------------|-----------------------|
| 1303446 | NPW | Walker Lake | 07/10/2023 10:10 AM | 07/10/2023 |

Laboratory Information:

Incubation: 7/10/23 18:01

| <u>Method</u> | <u>Test</u> | <u>Result</u> | <u>Unit</u> | <u>PQL</u> | <u>Analyst</u> | <u>Analysis Date/Time</u> | <u>Lab ID</u> | <u>Description</u> |
|---------------|---------------------------|---------------|-------------|------------|----------------|---------------------------|---------------|----------------------|
| m-ColiBlue24 | E. coli (Enumeration) (4) | 408 | cfu/100mL | 0 | TC | 07/11/2023 05:50 PM | 7-23W14401 | East Shore (E) (SB2) |
| m-ColiBlue24 | E. coli (Enumeration) (4) | 440 | cfu/100mL | 0 | TC | 07/11/2023 05:52 PM | 7-23W14402 | West Shore (E) (SB2) |

Date: 07/12/2023

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue
Suite 200
Dunmore, PA 18509




DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

(SB2): (SB2) Sample of water from bathing beach is considered contaminated per 28 Pa. Code §18.28.

Date: 07/12/2023

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT