

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
9377835	NPW	Walker Lake	07/07/2025 02:05 PM	07/07/2025

Laboratory Information:

Incubation: 7/7/25 16:28

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
SM 9222 B	Total Coliform (Enum) (4)	20	cfu/100mL	0	TC	07/08/2025 04:28 PM	7-25W44661	West Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	8	cfu/100mL	0	TC	07/08/2025 04:28 PM	7-25W44660	East Shore (E)

Date: 07/08/2025

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E):

(E) Results based upon colony counts outside the method's ideal range.

Date: 07/08/2025

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT