

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


<u>Chain of Custody Number</u>	<u>Sample Type</u>	<u>Project ID</u>	<u>Sample Date/Time</u>	<u>Accession Date</u>
4486089	NPW	Walker Lake	06/01/2026 05:05 PM	06/02/2026

Laboratory Information:

Incubation: 6/2/26 14:40

<u>Method</u>	<u>Test</u>	<u>Result</u>	<u>Unit</u>	<u>PQL</u>	<u>Analyst</u>	<u>Analysis Date/Time</u>	<u>Lab ID</u>	<u>Description</u>
m-ColiBlue24	E. coli (Enum) (4)	16	cfu/100mL	0	TC	06/03/2026 02:32 PM	6-26W58159	East Shore
m-ColiBlue24	E. coli (Enum) (4)	<4	cfu/100mL	0	Sub	06/03/2026 02:32 PM	6-26W58160	West Shore

Date: 06/04/2026

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT


1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 06/04/2026

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT