

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
8196709	NPW	Walker Lake	05/21/2025 03:45 PM	05/22/2025

Laboratory Information:

Incubation: 5/22/25 15:21

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	<4	cfu/100mL	0	TC	05/23/2025 03:17 PM	5-25W41964	East Shore
m-ColiBlue24	E. coli (Enumeration) (4)	<4	cfu/100mL	0	TC	05/23/2025 03:17 PM	5-25W41965	West Shore

Date: 05/23/2025

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT